| Technical Service Bulletin | | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| Model Year(s) Affe | ected | Model(s) Affected | TSB # | |
| 7/13/04 - 1/18/05 | | Spartan K2 Chassis | 286 | |
| Brand | | | Туре | |
| American Star | | Mountain Aire | All 🗖 TT 🗖 | |
| Dutch Star | | Kountry Aire | | |
| Kountry Star | | Essex | DP■ DB□ | |
| Northern Star | | London Aire | | |
| Air Conditioning & Heating Electrical Components | | | | |
| □ Appliances & Accessories □ Exterior Components | | | | |
| ıre | Interior Components | | | |
| nts | ſ | Plumbing & Bath Components | | |
| ponents | ſ | Windows, Awnings, Vents, & Doors | | |
| Description of Problem | | | | |
| Steering wheel circuit board replacement : Spartan K2 Chassis equipped with driver memory options have the potential for radio frequency interference with certain 2-way radios and the memory function controller, where activation of the memory options could occur without knowledge or input from the operator. | | | | |
| Recommended Solution | | | | |
| attached repair directions | | 5 | itional information | |
| | Model Year(s) Affe 7/13/04 – 1/18 Brand American Star Dutch Star Kountry Star Northern Star a Heating essories are its ponents Desc pard replacement : pped with driver memory s and the memory function re or input from the operation Recor | Model Year(s) Affected 7/13/04 – 1/18/05 Brand American Star Dutch Star Dutch Star Dutch Star Kountry Star Northern Star Northern Star tatas C Heating tatached repair directions. Contact reserves | Model Year(s) Affected Model(s) Affected 7/13/04 – 1/18/05 Spartan K2 Chassis Brand Brand American Star Mountain Aire Dutch Star Kountry Aire Dutch Star Kountry Aire Kountry Star Essex Northern Star London Aire at Heating Electrical Components essories Exterior Components interior Components Plumbing & Bath Comp ponents Plumbing & Bath Comp ponents Windows, Awnings, Ver Description of Problem Description of Problem bard replacement : Speed with driver memory options have the potential for radio free s and the memory function controller, where activation of the mater or input from the operator. | |

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.



Spartan Chassis, Inc. Customer Service Group

February 18, 2005

Re: Notice of Campaign Service Bulletin: CSB05-390-001

Dear Valued Customer,

A recent decision was made to issue a Campaign Service Bulletin which addresses the condition of a steering wheel circuit board replacement. There is a potential for radio frequency interference with certain 2-way radios and the memory function controller, where activation of the memory options could occur without knowledge or input from the operator.

Your satisfaction with our product is important to us. We are initiating this contact with you so that you will, at your earliest opportunity, take your vehicle in for service. In doing so, we can be certain that you have the best product available for optimal performance.

Carefully follow the instructions below:

Contact one of the Spartan Authorized Service Centers described on the attached list to arrange for an appointment. You can also call Spartan Chassis Customer Service 1-800-543-4277 (option 1); have your VIN (Vehicle Identification Number) available (this is listed on the upper left portion of the address label). A Spartan representative will advise you as to what your vehicle requires.

Although <u>this is not a recall</u>, Spartan Chassis is committed to serving you with your best interests in mind.

Best Regards,

Wayne Ridge Product Improvement Administrator Spartan Chassis, Inc.

Should the servicing facility have any billing questions, call Wayne Ridge at 517-543-6400 ext.445



Spartan Chassis, Inc. Customer Service Group