

NEWMAR CORPORATION

WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN									
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #	
2/15/90		1989-1990			TOWABLE			29	
BRAND					TYPE				
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input checked="" type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input type="checkbox"/>	T T <input checked="" type="checkbox"/>	F W <input checked="" type="checkbox"/>			
NewAire <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input checked="" type="checkbox"/>	London Aire <input type="checkbox"/>	C A <input type="checkbox"/>	D P <input type="checkbox"/>	D B <input type="checkbox"/>			
<input type="checkbox"/> Air Conditioning & Heating					<input type="checkbox"/> Electrical Components				
<input type="checkbox"/> Appliances & Accessories					<input type="checkbox"/> Exterior Components				
<input type="checkbox"/> Cabinets & Furniture					<input type="checkbox"/> Interior Components				
<input type="checkbox"/> Chassis Components					<input type="checkbox"/> Plumbing & Bath Components				
<input type="checkbox"/> Construction Components					<input type="checkbox"/> Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM									
Problem with 16X7 white spoke wheels developing leaks at welds.									
RECOMMENDED SOLUTION									
If a customer has this problem, Newmar will authorize replacement of all wheels on a unit with 16X6 wheels. The mfg. of these wheels feels this is a stronger wheel and is willing to replace complete set of wheels if the customer suffers failure with the 16X7 wheels. The wheels should be ordered from Newmar's parts department and the defective wheels returned.									

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT

Spring (INNER)

A. $3\frac{3}{8}$ " x $3\frac{3}{4}$ " Rod

B. $9\frac{1}{16}$ " x $1\frac{1}{2}$ " Rod

C. $3\frac{3}{8}$ " x $11\frac{1}{2}$ " Rod

(Cut By Newmar) $3\frac{3}{8}$ " x $7\frac{1}{2}$ " Rod

D. $3\frac{3}{8}$ " x 9" Rod

USED IN

NEWMAR INDUSTRIES, INC. Post Office Box 30, Nappanee, IN 46550	
<i>L.A. Automatic Door Ctr.</i>	
TITLE: <i>Actuator Rod Assy.</i>	
DATE: <i>8-17-89</i>	SCALE: <i>None</i>
DRAWN BY: <i>C. Reed</i>	
<i>material steel</i>	