TECHNICAL SERVICE BULLETIN						
DATE ISSUED	MODEL Y	MODEL YEAR(S) AFFECTED		MODEL(S) AFFECTED		
4/13/87	13/87 1987		ALL		3	
BRAND				Түре		
All 🗖 Americ	can Star 🔳	Kountry Star 📕 I	Dutch Star 🛛	All 🗖 T	Т П	
NewAire Mountain Aire Kountry Aire Lon			London Aire 🗖	C A 📕 D	P■ DB□	
□ Air Conditioning & Heating □ Electrical Components						
□ Appliances & Accessories ■ Exterior Components						
Cabinets & FurnitureInterior Components						
Chassis Components Plumb			Plumbing 8	& Bath Components		
□ Construction Components □ Windows,				Awnings, Vents, & Doors		
DESCRIPTION OF PROBLEM Onan generator installation.						
RECOMMENDED SOLUTION						
1. Purchase a tray and slide through an Onan dealer or through the Newmar Parts Department. The part number is BP-12/151.						
		nerator 4000 complete . This can also be pur				

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.