

# NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN									
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #	
2/21/92		1991-1992			ALL			49	
BRAND						TYPE			
All <input type="checkbox"/>		American Star <input checked="" type="checkbox"/>	Kountry Star <input checked="" type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input type="checkbox"/>		T T <input checked="" type="checkbox"/>	F W <input checked="" type="checkbox"/>	
NewAire <input type="checkbox"/>		Mountain Aire <input checked="" type="checkbox"/>	Kountry Aire <input checked="" type="checkbox"/>	London Aire <input checked="" type="checkbox"/>	C A <input type="checkbox"/>		D P <input type="checkbox"/>	D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating					<input checked="" type="checkbox"/> Electrical Components				
<input type="checkbox"/> Appliances & Accessories					<input type="checkbox"/> Exterior Components				
<input type="checkbox"/> Cabinets & Furniture					<input type="checkbox"/> Interior Components				
<input type="checkbox"/> Chassis Components					<input type="checkbox"/> Plumbing & Bath Components				
<input type="checkbox"/> Construction Components					<input type="checkbox"/> Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM									
For safety sake, on units with slide outs that are put into shows, this would be a good way to eliminate people running slide outs in and out and the chance of someone getting caught in the room.									
RECOMMENDED SOLUTION									
Add a switch per the enclosed print. If you have any questions, please contact the Newmar Service Department.									

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

# NEWMAR CORPORATION WARRANTY DEPARTMENT

