

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN									
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #	
5/11/92		1992			ALL			51	
BRAND					TYPE				
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input checked="" type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>			
NewAire <input type="checkbox"/>	Mountain Aire <input checked="" type="checkbox"/>	Kountry Aire <input checked="" type="checkbox"/>	London Aire <input checked="" type="checkbox"/>	C A <input checked="" type="checkbox"/>	D P <input type="checkbox"/>	D B <input type="checkbox"/>			
<input type="checkbox"/> Air Conditioning & Heating					<input type="checkbox"/> Electrical Components				
<input type="checkbox"/> Appliances & Accessories					<input type="checkbox"/> Exterior Components				
<input type="checkbox"/> Cabinets & Furniture					<input type="checkbox"/> Interior Components				
<input checked="" type="checkbox"/> Chassis Components					<input type="checkbox"/> Plumbing & Bath Components				
<input type="checkbox"/> Construction Components					<input type="checkbox"/> Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM									
Fuel filter leaking on Spartan chassis.									
RECOMMENDED SOLUTION									
Fuel filter #FS 5038 should be replaced with filter #1280. Please contact the Newmar Service Department at 800.837.3708 or Spartan Motors at 800.543.4334 for a replacement filter.									

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.