

NEWMAR CORPORATION WARRANTY DEPARTMENT


TECHNICAL SERVICE BULLETIN			
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #
5/19/92	1992	ALL	53
BRAND		TYPE	
All <input type="checkbox"/>	American Star <input checked="" type="checkbox"/>	Kountry Star <input checked="" type="checkbox"/>	Dutch Star <input type="checkbox"/>
NewAire <input type="checkbox"/>	Mountain Aire <input checked="" type="checkbox"/>	Kountry Aire <input checked="" type="checkbox"/>	London Aire <input checked="" type="checkbox"/>
		All <input type="checkbox"/>	TT <input checked="" type="checkbox"/>
		CA <input checked="" type="checkbox"/>	DP <input type="checkbox"/>
		FW <input checked="" type="checkbox"/>	DB <input type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating <input type="checkbox"/> Appliances & Accessories <input type="checkbox"/> Cabinets & Furniture <input type="checkbox"/> Chassis Components <input checked="" type="checkbox"/> Construction Components		<input type="checkbox"/> Electrical Components <input type="checkbox"/> Exterior Components <input type="checkbox"/> Interior Components <input type="checkbox"/> Plumbing & Bath Components <input type="checkbox"/> Windows, Awnings, Vents, & Doors	
DESCRIPTION OF PROBLEM			
Slide out locking arms.			
RECOMMENDED SOLUTION			
All units coming off line after April 1, 1992 will have the new type of arms, which do not require the lock pin anymore. The new type of arms has been built with a ratchet so it will lock automatically.			

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

72185 COUNTY ROAD 3
NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924
FAX 219.773.2007



□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.