

# NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #				
4/22/93	1993	ALL	75				
BRAND		TYPE					
All <input checked="" type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input checked="" type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>	
NewAire <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input type="checkbox"/>	C A <input type="checkbox"/>	D P <input type="checkbox"/>	D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components			
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Cabinets & Furniture				<input checked="" type="checkbox"/> Interior Components			
<input type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
Battery drain on LP leak detector. How to disarm detector.							
RECOMMENDED SOLUTION							
<p>Whenever an LP leak detector is installed there will also be a method of disarming the detector in order to not drain the battery. This will be done with the battery disconnect when there is a battery disconnect in the unit. If no battery disconnect is in the unit, a switch will be located close to the range with a note beside it to only shut the switch off when the unit is put in storage.</p> <p>Tag: LP detector switch is to be turned off only while unit is in storage.</p>							

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.