TECHNICAL SERVICE BULLETIN													
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED				TSB #				
6/22/93		1992-1993			All				77				
B				RAND						Түре			
All		\merio	can Star 🛛 Kountry Star 🗖		Ι	Dutch Star 🛛		All 🗖	Т	T 🗖 F W 🗖		ו	
Nev	wAire 🗖 N	Mount	ain Aire 🛛	Kountry Aire	Ι	Lon	don Aire□	САП	D	Р□	DB 🗆	ב	
Air Conditioning & Heating Electrical Components													
	Appliances & Accessories						Exterior Components						
	Cabinets & Furniture						□ Interior Components						
	Chassis Com	nts				Plumbing 8	e Bath Components						
	Construction				Windows, A	Awnings, Vents, & Doors							
DESCRIPTION OF PROBLEM Burned out circuit boards on water heaters.													
RECOMMENDED SOLUTION													
				oking up battery, r out circuit boards				the ground	wire	e to the	battery fir	st.	

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.