

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN						
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #			
6/22/93	1993-1994	ALL	79			
BRAND		TYPE				
All <input checked="" type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input type="checkbox"/>	T T <input checked="" type="checkbox"/>	F W <input checked="" type="checkbox"/>
NewAire <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input type="checkbox"/>	C A <input type="checkbox"/>	D P <input type="checkbox"/>	D B <input type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating				<input checked="" type="checkbox"/> Electrical Components		
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components		
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components		
<input type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components		
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors		
DESCRIPTION OF PROBLEM						
12 volt not working in unit. Breaker must be reset.						
RECOMMENDED SOLUTION						
Reset breaker per enclosed print.						

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT

THE RESETTABLE BREAKERS ARE LOCATED WITHIN 18" OF THE SOURCE OF POWER. THIS IS THE CONVERTER AND THE BATTERY. WHEN EITHER OF THE BREAKERS ARE SHUT DOWN THEY MUST BE MANUALLY RESET. TO FIND THE BREAKERS FOLLOW THE LINE FROM THE BATTERY OR CONVERTER FOR APPROXIMATELY 18". THIS MAY LEAD TO A JUNCTION BOX OR TO A CABINET INSIDE THE UNIT OR SIMILAR LOCATION. MANUALLY RESET THE BREAKER AS SHOWN IN FIGURE 2.




FIG. 1
TYPICAL PRINT INFO.




FIG. 2
TOP VIEW OF BREAKER