


NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN																			
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #											
8/6/93		1992-1993			ALL			83											
BRAND					TYPE														
All	<input type="checkbox"/>	American Star	<input type="checkbox"/>	Kountry Star	<input checked="" type="checkbox"/>	Dutch Star	<input type="checkbox"/>	All	<input type="checkbox"/>										
NewAire	<input type="checkbox"/>	Mountain Aire	<input checked="" type="checkbox"/>	Kountry Aire	<input checked="" type="checkbox"/>	London Aire	<input checked="" type="checkbox"/>	T T	<input type="checkbox"/>										
								F W	<input type="checkbox"/>										
								C A	<input checked="" type="checkbox"/>										
								D P	<input type="checkbox"/>										
								D B	<input type="checkbox"/>										
<table border="0"><tr><td><input type="checkbox"/> Air Conditioning & Heating</td><td><input type="checkbox"/> Electrical Components</td></tr><tr><td><input type="checkbox"/> Appliances & Accessories</td><td><input checked="" type="checkbox"/> Exterior Components</td></tr><tr><td><input type="checkbox"/> Cabinets & Furniture</td><td><input type="checkbox"/> Interior Components</td></tr><tr><td><input type="checkbox"/> Chassis Components</td><td><input type="checkbox"/> Plumbing & Bath Components</td></tr><tr><td><input type="checkbox"/> Construction Components</td><td><input type="checkbox"/> Windows, Awnings, Vents, & Doors</td></tr></table>										<input type="checkbox"/> Air Conditioning & Heating	<input type="checkbox"/> Electrical Components	<input type="checkbox"/> Appliances & Accessories	<input checked="" type="checkbox"/> Exterior Components	<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components	<input type="checkbox"/> Chassis Components	<input type="checkbox"/> Plumbing & Bath Components	<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors
<input type="checkbox"/> Air Conditioning & Heating	<input type="checkbox"/> Electrical Components																		
<input type="checkbox"/> Appliances & Accessories	<input checked="" type="checkbox"/> Exterior Components																		
<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components																		
<input type="checkbox"/> Chassis Components	<input type="checkbox"/> Plumbing & Bath Components																		
<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors																		
DESCRIPTION OF PROBLEM																			
All units equipped with auto leveling jacks must have control box grounded to frame. All auto leveling jacks with Fenner stone power motors must also have ground added to it.																			
RECOMMENDED SOLUTION																			
Check for these two problems. See print on how to install grounds. Contact the Newmar Service Department representatives if you need to order kit for this repair. Newmar will pay 1.5 hours to make this change.																			

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT


GROUNDING INSTRUCTIONS 610 CONTROL BOX



MP0999
07-21-93

NEWMAR CORPORATION WARRANTY DEPARTMENT

GROUND CABLE INSTALLATION FOR STONE PUMPS



CONNECT GROUND CABLE STRAP FROM NEGATIVE ("−")
MOTOR TERMINAL TO PUMP CHANNEL MOUNTING BOLT (A).
IF PUMP CHANNEL IS WELDED TO FRAME, CONNECT
GROUND CABLE STRAP TO A PUMP MOUNTING BOLT (B).
A 3/8 INTERNAL STAR LOCKWASHER MUST BE USED
BETWEEN GROUND CABLE STRAP TERMINAL/PUMP CHANNEL
AND BETWEEN GROUND CABLE STRAP TERMINAL/BOLT HEAD
OR NUT.

RAP0838 GROUND STRAP KIT

MP0883
07-21-93