

NEWMAR CORPORATION WARRANTY DEPARTMENT

| TECHNICAL SERVICE BULLETIN | | | | | | | | | |
|--|---|--|--------------------------------------|---|---|------------------------------|--|-------|--|
| DATE ISSUED | | MODEL YEAR(S) AFFECTED | | | MODEL(S) AFFECTED | | | TSB # | |
| 3/10/94 | | 1992-1994 | | | Class A | | | 92 | |
| BRAND | | | | | TYPE | | | | |
| All <input type="checkbox"/> | American Star <input type="checkbox"/> | Kountry Star <input checked="" type="checkbox"/> | Dutch Star <input type="checkbox"/> | All <input type="checkbox"/> | T T <input type="checkbox"/> | F W <input type="checkbox"/> | | | |
| NewAire <input type="checkbox"/> | Mountain Aire <input checked="" type="checkbox"/> | Kountry Aire <input checked="" type="checkbox"/> | London Aire <input type="checkbox"/> | C A <input checked="" type="checkbox"/> | D P <input type="checkbox"/> | D B <input type="checkbox"/> | | | |
| <input type="checkbox"/> Air Conditioning & Heating | | | | | <input type="checkbox"/> Electrical Components | | | | |
| <input type="checkbox"/> Appliances & Accessories | | | | | <input type="checkbox"/> Exterior Components | | | | |
| <input type="checkbox"/> Cabinets & Furniture | | | | | <input type="checkbox"/> Interior Components | | | | |
| <input type="checkbox"/> Chassis Components | | | | | <input type="checkbox"/> Plumbing & Bath Components | | | | |
| <input checked="" type="checkbox"/> Construction Components | | | | | <input type="checkbox"/> Windows, Awnings, Vents, & Doors | | | | |
| DESCRIPTION OF PROBLEM | | | | | | | | | |
| Tag axle brake lock up on Granning air suspensions. | | | | | | | | | |
| RECOMMENDED SOLUTION | | | | | | | | | |
| Make sure that if you change the vacuum hose to the Granning set up that you use a vacuum hose that has the SAE-J-1403 approved label. | | | | | | | | | |

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.