TECHNICAL SERVICE BULLETIN								
DATE ISSUED MODEL Y		'EAR(S) AFFECTED		MODEL(S)	AFFECTED	TSB #		
7/7/94	A11			All		97		
Brand					Түре			
All Americ	can Star 🛛	Kountry Star 🛛	Dut	ch Star 🛛	All 🗖 🐪	ГТ 🗖	FW 🗖	
NewAire 🛛 Mountain Aire 🗖 Kountry Aire 🗖			Lon	don Aire□	$C A \square D P \square D B \square$			
□ Air Conditioning & Heating				Electrical Components				
Appliances & Accessories				Exterior Components				
□ Cabinets & Furniture				Interior Components				
Chassis Components				Plumbing & Bath Components				
Construction Components				Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM								
RECOMMENDED SOLUTION								
Refer to Suburban TSI:	RV94-560 b	oulletin that is attache	d.					

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT




Dayton, Tennessee • Elkhart, Indiana

SERVICE BULLETIN



TO: Suburban Distributors Service Centers OEM Accounts

SUBJECT: SUBURBAN DYNATRAIL WATER HEATERS - ANODE ROD INFORMATION



Replacement of the anode rod is recommended when consumption or weight loss is greater than 75%. The sacrificial anode equalizes aggressive water action providing cathodic protection for the tank. The anode is a very important factor in tank life and should only be removed for inspection or draining.

OPERATING THE WATER HEATER WITHOUT THE ANODE, VOIDS SUBURBAN'S LIMITED WARRANTY.

Neal Stultz National Service Manager