



701 Ann Street N.W.
Grand Rapids, MI 49504
P) 800-878-7147
F) 616-361-9646

SERVICE BULLETIN

#011516


DATE: January 15, 2016

TO: Authorized Evans Tempcon Service Centers, OEM customer service personnel

SUBJECT: RV218076 Blower Motor to be replaced by RV218814 Blower Motor & Wheel Assy.

The blower motor (HV033208) on motor homes with an Evans Tempcon Inc. dash HVAC system is no longer available and is being replaced by our newly designed blower motor and wheel assembly. The motor remains the same but the blower wheel will now be made of plastic versus metal. Fit/form/function will remain the same. One notation; the original metal wheel is not interchangeable with the new plastic wheel. Once our original metal wheel stock is depleted, this new package will have to be ordered when the need for replacing just the wheel comes into play as well.

We have opted to go with this service package option due to a change in manufacturing – we are now purchasing the motor and wheel assembled from our supplier. This new assembly will actually provide better performance. This also eliminates time spent at the service end as they will no longer have to assemble and balance the motor and wheel.



RV218076 Blower Motor

To be replaced
by →



RV218814 Blower & Wheel Assembly

Any questions, please contact us at 800-878-7147, extension 844 or 811.