
ITEM #	QTY	NEWMAR #	DESCRIPTION
1	1	136982	MONITOR PANEL NADP 18



NOTE:

NO RESISTORS ON SLIDEOUT SWITCHES

Revision: REVERSED THE DRIVER AND PASSENGER AWNINGS SWITCHES AND ADDED By: B. B. Model: Sheet Drawn by: Checked by: NEWMAR CORP NADP J. S. R. W. P.O. Box 30, Nappanee, IN. 46550 RESISTOR NOTE PER (PCR #180630) Date: 5/30/17 I.D. # 2018\ DP\CODE\ELEC\ NA_MONITOR_PANELS Title: Date: Date: Revision: CHANGE LOCATION OF SWITCHES, DIA. CONN. AND WINEGARD CONTROL By: D. F. UNITS: INCHES MONITOR PANEL 12/29/16 Date: 2/14/17 TITLE BLOCK: 1-4FULTB REVERSED THE LOCATION OF THE SLIDE OUT SWITCHES