




ITEM #	QTY	NEWMAR #	DESCRIPTION
1	1	149084	FRONT CAP-BOX FRONT (Vendor #5257)



TOP VIEW




BACK VIEW
("B" SIDE)



*MAINTAIN .1875
MATERIAL THICKNESS
AT TRIM LINE PERIMETER

FRONT VIEW
("A" SIDE)



SIDE VIEW

NOTES:
MATERIAL THICKNESS IS: .1875"

NEWMAR CORP P.O. Box 30, Nappanee, IN. 46550 UNITS: INCHES TITLE BLOCK: 75TB	Model:	Sheet	Drawn by:	Checked by:	Revision: Added 4x12 notch to bottom driver side of front cap box 18" from center line	By: R. W.
	SSCC/SACC (SEE INDEX)	1 OF 1	H. Y.	R. R.	to prevent cap from sitting directly on wires running between cab and coach (PCR #202119)	Date:EC 11/5/19
	Title:	I.D. # 2020\ CC\PROFILE\PARTS\ FRONT_CAP_BOX	Date:	Date:	Revision: NEW PART NUMBER 149084 ILO 142801(ECO # 240)	By: H. Y.
	FRONT CAP BOX		12/12/18	12/13/18		Date:DE 6/17/19