


<i>ITEM #</i>	<i>QTY</i>	<i>NEWMAR #</i>	<i>DESCRIPTION</i>
1	1	162803	DRIV SW PAN SP NONTAG VT MT BK
2	1	119689	DOUBLE CUP HOLDER RUBBER INSR
3	1	142044	SWITCH "L" SERIES HOUSE BATT



NEWMAR CORP P.O. Box 30, Nappanee, IN. 46550 UNITS: INCHES TITLE BLOCK: 1TB	Model: (C975)(C980)	Sheet	Drawn by:	Checked by:	Revision: Updated part number to 162803 ILO 160810. Eliminated Petal Switch	By: N. T.
	VTDP (SPARTAN) 34' & 37'	1 OF 1	N. T.		and replaced with Engine Break Switch (2023 ECO #84)	Date:VK 5/3/22
	Title:	I.D. # 2023\COMPONENTS\162803	Date:	Date:	Revision:	By:
	DR CONSOLE SWITCH PANEL		4/29/22			Date: