Newmar Corporation

866.290.5371 Fax 574.773.2007

Date Issued		PIB#
12/16/2010	Procedure for returning Gustafson Lighting	004

• This pertains to all motorized and towable units still in warranty returning

Product Information

Please note, when replacing Gustafson fluorescent lights, please follow these requests.

- There must be 4-5 inches of wire left coming out of the fixture to allow for proper testing.
- There must be no writing with a permanent marker anywhere on the light fixture.



<u>Improper wire length</u> – testing can't be performed.



Proper wire length - can be returned for warranty replacement.

Common Newmar Part Numbers for Gustafson Fluorescent Lighting.

51838 # 51839 # 84475 # 84476 # 116686 # 116687