Newmar Corporation

Dealer 866-290-5371 Customer 800-

Product Information Bulletin								
Date Issued				•				PIB #
7/6/2015		Xantrex Inverter Remote						40
	YEAR	/	BRAND	/	TYPE	/	MODEL #	

2015 King Aire Units with Xantrex inverter installation:

Information: This PIB was created to inform our dealers.

1. To set up and troubleshoot Xanterx inverters installed on 2015 King Aire units a Remote Panel is needed.

https://newgle.newmarcorp.com/yy/Xantrex Inverter Update Process to V3.47.00 (Xantrex Version 3.03 BN13) Newgle link on how to use remote to setup inverters after inverter update

2. This Remote can be purchased through Newmar parts department.

Newmar part # 022905

Cost: \$220.50

