TECHNICAL SERVICE BULLETIN								
DATE ISSUED				MODEL(S) AFFECTED			TSB #	
10/24/95	1996			ALL			124	
Brand				Түре				
All 📕 American Star 🗖 Kountry Star 🗖		Dut	Dutch Star 🗖 All 🗖 TT 🗖 FV		FW 🗖			
NewAire 🛛 Mountain Aire 🗖 Kountry Ai		Kountry Aire	Lon	don Aire□	САП	D₽□	DB 🗖	
 Air Conditioning & Heating Electrical Components 								
 Appliances & Accessories 				Exterior Components				
□ Cabinets & Furniture				☐ Interior Components				
Chassis Components				Plumbing & Bath Components				
Construction Components				□ Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM Dometic, Duo-Therm, and A&E products are changing their phone numbers for customers and dealers. These								
numbers will go into e		25.						
RECOMMENDED SOLUTION								
The new dealer hotlind not give the dealer nur questions answered. I	nber to the cu	stomer as this will tie	up tl	ne phone and	make it harde	er to get	your	

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.