

TECHNICAL SERVICE BULLETIN									
DATE ISSUED MODEL YI		ear(s) Affected		MODEL(S) AFFECTE			TSB #		
3/15/89	1989			ALL			16		
BRAND					Түре				
All 🗖 Americ	can Star 🛛	Kountry Star 🛛	Dut	ch Star 🛛	All	Τ'	Г 🗖	FW 🗖	
NewAire 🛛 Mountain Aire 🗖 Kountry Aire 🗖				don Aire				DB 🗖	
$\Box$ Air Conditioning $\delta$		Electrical Components							
Appliances & Accessories				Exterior Components					
Cabinets & Furniture				Interior Components					
Chassis Components				☐ Plumbing & Bath Components					
Construction Components				☐ Windows, Awnings, Vents, & Doors					
DESCRIPTION OF PROBLEM How to hook up the TV, VCR, and the satellite dish.									
RECOMMENDED SOLUTION									
Attached are seven diffe	erent TV, VCI	<b>ξ</b> , and satellite dish p	rints	on how these	e are wired.				




If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.




LA. (Cable & VCR Prep Studand) with set. Dish option 3-14-89 OR

CR

# NEWMAR CORPORATION WARRANTY DEPARTMENT







KA standard Systen With optional Cable hookup 3-14-89 OR

#### 72185 COUNTY ROAD 3 NAPPANEE, IN 46550


# NEWMAR CORPORATION WARRANTY DEPARTMENT




STD LA. (VCR Prep std.) 3-14-89 CR



K.A. V.C.R. Prep 3-14-89 CR



KA std. System With Sat Dish Option 3-14-89 NP



KA with Cable and sat Dish Option 3-14-89 OR

