

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #				
2/24/00	Freightliner Chassis	2000	197				
BRAND		TYPE					
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input checked="" type="checkbox"/>	Dutch Star <input checked="" type="checkbox"/>	All <input type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>	
NewAire <input type="checkbox"/>	Mountain Aire <input checked="" type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input checked="" type="checkbox"/>	C A <input checked="" type="checkbox"/>	D P <input checked="" type="checkbox"/>	D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components			
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components			
<input checked="" type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
Freightliner custom chassis updates.							
RECOMMENDED SOLUTION							
Please refer to the attached information.							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

72185 COUNTY ROAD 3
NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924
FAX 219.773.2007



A Subsidiary of **FREIGHTLINER**
CORPORATION

PRODUCT INFORMATION BULLETIN

Freightliner Custom
Chassis Corporation
552 Hyatt Street
Gaffney, South Carolina 29341
864.487.1700 Phone
864.487.1718 Fax

TO: RV OEM's
& Shuttle Bus OEM's

Date: December 22, 1999
Bulletin No.: FRT-RV1299
Type: Product Bulletin
Model: XC, MC, VCL, XB, MB
CCN: N/A

SUBJECT: Customer Assistance Center Label

Starting immediately, Freightliner will provide a label in the owner's packet that gives the phone number for the "Freightliner Customer Assistance Center". Freightliner requests that each O.E.M. place this label somewhere on the coach where it is visible from outside the coach such as a lower corner of a windshield, or back by the radiator.

The feedback Freightliner has been receiving from the market is that the retail customer doesn't know who to call with questions about their chassis. By supplying this label, it is our intent to alleviate this confusion.

If you have any questions please contact your Technical Sales Manager.

Sincerely

Dean Schaper
Product Manager

PRD10-99.doc

Freightliner Corporation is a
DaimlerChrysler Company

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

72185 COUNTY ROAD 3
NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924
FAX 219.773.2007



A Subsidiary of **FREIGHTLINER**
CORPORATION

PRODUCT INFORMATION BULLETIN

Freightliner Custom
Chassis Corporation
552 Hyatt Street
Gaffney, South Carolina 29341
864.487.1700 Phone
864.487.1718 Fax

TO: RV OEM's

Date: February 4, 2000
Bulletin No.: FRT-RV2-00
Type: Product Bulletin
Model: XC, MC, VCL
CCN: N/A

SUBJECT: CAT Emblem

Chassis Powered with the CAT 3126 engine are now being shipped with a CAT DIESEL POWER emblem in the owners packet. The emblem like the Freightliner emblems comes with a self adhesive back and is intended to be installed by the coach builder.

Sincerely

A handwritten signature in cursive script that reads "Dean Schaper".

Dean Schaper
Product Manager

PRD10-99.doc

Freightliner Corporation is a
DaimlerChrysler Company

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.