

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED		MODEL YEAR(S) AFFECTED		MODEL(S) AFFECTED		TSB #	
3/1/93		1992-1993		ALL		70	
BRAND				TYPE			
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input checked="" type="checkbox"/>	Dutch Star <input checked="" type="checkbox"/>	All <input type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>	
NewAire <input type="checkbox"/>	Mountain Aire <input checked="" type="checkbox"/>	Kountry Aire <input checked="" type="checkbox"/>	London Aire <input checked="" type="checkbox"/>	C A <input checked="" type="checkbox"/>	D P <input type="checkbox"/>	D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components			
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components			
<input checked="" type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
Check transmission cooling lines leaking on Chevrolet chassis on add-on transmission cooler.							
RECOMMENDED SOLUTION							
Check transmission cooler line to see that it has the correct hose that has the Valley 2058-00 Goodyear printed on it or the number SAE 100 RC on the hose. If the hose doesn't have this on it, change the hose. This hose can be sent out through our Parts Department. This should take .5 to change the hose. Newmar will pay .25 to check to see if it has the correct hose on it. If the wrong hose is on it, please contact your service representative for authorization to do the work or if you have any questions.							

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.