

ITEM #	QTY	NEWMAR #	DESCRIPTION	
1	1	135197	72x50 DOOR; OUTER FRAME BLK	
2	1	118158	30# Dynamic Strut	
3	1	91680	Banana Strut Bracket	


1. PRINT IS SHOWING DOOR CLOSED & FROM EXTERIOR.

2. DOOR HAS DUAL LATCH SYSTEM

3. OUTER FRAME OF DOOR TO BE BLACK.







Date:

NEWMA	R	CORP
P.O. B Nappanee,		
UNITS:	INCH	ES

TITLE BLOCK: 1TB

NOTES:

Model:	Sheet	Drawn by:	Checked by:
CS CA 3911	1 OF 2	R. R.	J. S.
Γitle:	I.D. # 2017\ CA\PROFILE\		Date:
DOOR, WheelChair Lift	CA\PROFILE\ DOOR_WHEELCHAIR_LIFT	4/19/16	4/25/16

Newmar Supplied: Plunger Switch ~

Top of coach floor; door

sets  $1\frac{1}{2}$ " down into floor

y:	Revision:	Ву:
		Date:
	Revision:	Ву:

VIEW B