


ITEM #	QTY	NEWMAR #	DESCRIPTION
1	1	145221	DASH CENTER STACK MONITOR ASSY
2	1	170036	ASA CAMERA MONITOR
3	1	147972	RADIO DASH SONY AM/FM/BT
3	1	136098	RADIO DAS XITE XSG2NA-X2 W/NAV

OPT J338



NEWMAR CORP P.O. Box 30, Nappanee, IN. 46550 UNITS: INCHES TITLE BLOCK: 1TB	Model: (J338)	Sheet 1 OF 1	Drawn by: N. T.	Checked by: D. E.	Revision: NEW PRINT FOR 2024; OLD PATH:2022\COMPONENTS\KS_CENTER_STACK; REPLACED PART #150257	By: N. T.
	Title: KSDP				"MONITOR 7" LCD BACKUPTURN CAM" WITH PART #170036 ASA CAMERA MONITOR. (2024 ECO #760)	Date:DE 1/16/24
		I.D. # 2024\COMPONENTS\KS_CENTER_STACK	Date: 1/4/24	Date: 1/16/24	Revision:	By:
						Date: