




WALL MOUNTED READING LIGHT LOCATED ON FRONT DS AND DDS SIDEWALL REMOVED AND R. R.
 REPLACED WITH A CEILING MOUNTED HALOGEN LIGHT ABOVE DRIVER AND PASSENGER SEAT PER ECO #202 6/3/08
 REVISED FUEL PUMP SWITCH & LIGHT LOCATIONS IN REAR CARGO AREAS R. R.
 (PCR #72494) 5/29/08 R. R.
 CENTER DINETTE LIGHT ON TABLE, DELETE HALOGEN (ECO #363) 5/28/08 R. R.
 ADD OPTION C844 (ECO #310) 5/23/08 R. R.
 FLOURESCENT ILD INCANDESCENT (ECO #43), HALOGEN ILD DIRECTIONAL R. R.
 W/ OPT. K020 (ECO #24) 3/20/08 C. L.
 REVISED TO REFLECT WALK-THRU CHANGES, ADDED CSA INFORMATION (ECO #K9) 2/18/08 C. L.
 REVISED BR CAB LIGHTING (ECO #674) (ECO #383) 2/7/08 R. R.
 MOVE THERMOSTAT AWAY FROM DOOR TO DRY BAR SIDE R. R.

(C844XD110) (K020)
 CS CA 3920 (H188)(J378) 1 DF 3 C. L. R. R.
 2009\CA\CDMEVELEC\CS\3920
 12V WIRING DIAGRAM 10/17/07 10/25/07