2009 Newmar Exterior Graphics Package

2009 X-Aire FW 9B841 Yellow Flame





Skin: Exterior Skin is Gelcoat; Newmar Corporation does not recommend performing spot or panel repairs with paint. Only Gelcoat should be used.

All graphics on this unit are tape as listed above.