72185 County Road 3 Nappanee, IN 46550

Newmar Corporation Warranty Department

	800.858.4924
Fax	219 773 2007

		Technical	Serv	/ic	e Bulletin				
	Date Issued	Model Year(s) Affect	ted		Model(s) Affect	ted		_	TSB#
	10/20/2006	2005-2006			All K2 chass	sis			264
		Brand		1				Т	уре
All		American Star		1	Mountain Aire		Al	1 🗆	ТТП
		Dutch Star		ŀ	Country Aire		F'	w 🗆	САП
		Kountry Star		I	Essex		D	р ■	DB■
Sco	ttsdale 🗆	Northern Star		I	London Aire			. –	
	Air Conditioning &	& Heating			Electrical Compos	nents			
	Appliances & Acco	essories			Exterior Compon	ents			
	Cabinets & Furnit	ure			Interior Compone	ents			
	Chassis Componer	nts			Plumbing & Bath	Compo	oner	nts	
	Construction Com	ponents			Windows, Awning	gs, Ven	ts, &	k Door	S
		Descr	ription of	Pro	blem				
		Air system can du	шр мпен	. VCI	iicie is iii modoli.				
		Recom	mended	d Sc	olution				
	See manu	facture attached repair inst	ruction.	Rep	air wiring to HWH	levelin	g sy	stem.	



CSB05-390-002

November, 2005 Page 1 of 3

CAMPAIGN SERVICE BULLETIN

SUBJECT: Wiring- HWH Air Leveling System

APPLIES TO: Certain Spartan Chassis K2 Models Equipped with an HWH Computer

Controlled Air Leveling System and a Body Manufactured by Newmar, with a VDM (Vehicle Date of Manufacture) from April 20, 2005

through August 29, 2005.

CONDITION: The Air System is Capable of Dumping When Vehicle is Traveling

Over 8 MPH

CAUSE: Incorrect Lockout Wiring Circuit

CORRECTION: Install logic converter relay jumper harness.

PART / SERVICE INFORMATION:

Labor Time: .5 Hr.

QTY. Part Number Description

S-1727-001 Kit- HWH Lockout

Kit #S-1727-001 Contains:

QTY.Part NumberDescription12595-GG5AHarn- HWH Relay Logic Converter1T30RO6.0" Tie Strap

1 CSB05-390-002 Document Instructions

PLEASE READ THE ENTIRE BULLETIN BEFORE PROCEEDING WITH ANY WORK.

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

SPARTAN CHASSIS, INC.


CSB05-390-002

November, 2005 Page 2 of 3

CAMPAIGN SERVICE BULLETIN

STEP-BY-STEP INSTRUCTIONS:

- 1. Observe all industry safety standards and secure vehicle to allow for installation of a jumper harness to the HWH interface connector.
- 2. Open compartment in front of the left front wheel to gain access to the HWH generator slide panel control.



GENERATOR SLIDE OPERATOR'S PANEL FIG. 2-1

- 3. Open the generator slide out to gain access to the area where the harness jumper is to be installed.
- 4. Locate the 7-way HWH controller interface connector as shown in FIG. 2-2. It is generally positioned in the area beneath the brake treadle.
- 5. Unplug the connectors and plug the harness jumper in between the connectors.



HWH INTERFACE CONNECTOR FIG. 2-2

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

CSB05-390-002

November, 2005 Page 3 of 3

CAMPAIGN SERVICE BULLETIN



<u>2595-GG5A INSTALLED</u> <u>FIG. 3-1</u>

- 6. Secure the relay with a zip tie.
- 7. Close generator slide out and close the compartment door.
- 8. Test drive unit to verify correct operation- chassis will not "dump" above 8 MPH.

Technical Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of product specific nature in conjunction with industry standards. Professional Technicians are appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

2530-GG5A with Vantive 8-30-05

Captured at OEM's on listed date
Captured in production per change 2974-1-1 on 08/22/05

	19195							
	יא רר	l ast Name or						
VINNUM	ORDE	Company Name	First Name	Address	City	State	diZ	Phone
4VZAT1C966C052749	52749	Jones	Dale	51 N. Eastridge Drive	St. George	5	84790	
4VZAT1C966C052251 !	52251	Tom Johnson Camping Center		1885 US 70 West	Marion	S	28752	7104 455 1440
	52252	Midway Motor		5590 S. Division Ave.	Grand Rapids	Ξ	49548	616 534 9641
	52313	Alpin Haus		103 Sitterly Rd	Clifton Park	ž	12065	518 371 2211
4VZAT1C946C052314 (52314	Liesure Tyme - ME		1490 Hwy 98 West	Mary Ester	귙	32569	850 581 0880
	52315	Kruse	Gary Lynn & Lori Ann	22690 Grande View Ave.	Glenwood	≰	51534	712 527-3012
	52391	North Trail		5270 Orange River Blvd	Fort Myers	귙	33905	239 693 8200
	52392	Marney	Perry L & Donna J	4539 SE Oak Bend Dr	Berryton	S S	66409	785 862-5926
	52393	Midway Motor		5590 S. Division Ave.	Grand Rapids	Ξ	49548	616 534 9641
	52514	Bohls	John E.	11215 Stormy Ridge Rd.	Austin	×	78739	512 971-2440
4VZAT1C936C052515 !	52515	Ellis	Hobert N & Patricia	6225 N Coast Hwy 101 #82	Newport	OR	97365	541 265-8294
4VZAT1C956C052516 !	52516	Newell	Richard A	10991 E Oatman Dr	Scottsdale	ΥZ	85262	480 226-0820
	52591	RV Corral		1890 Hwy 99 North	Eugene	OR	97402	541 689 9204
	52592	Beaudrey RV Company		3200 E. Irvington Road	Luscon	ΑZ	85714	520 889 6000
	52593	Coachlight		5327 Garrison Ave.	Cathage	Ø	64836	417 358 7444
4VZAT1C916C052691 (52691	Beaudrey RV Company		3200 E. Irvington Road	Luscon	ΑZ	85714	520 889 6000
4VZAT1C936C052692 (52692	Beaudrey RV Company		3200 E. Irvington Road	Tuscon	ΥZ	85714	520 889 6000
	52693	Beaudrey RV Company		3200 E. Irvington Road	Tuscon	ΑZ	85714	520 889 6000
	52747	Gensmer	Willis & Carol	PO Box 1126	Winona	Z	55987	
		Alpine		19380 Monterey Road	Morgan Hill	S	95037	408 779 4511
4VZAT1C976C052808 (52808	Beaudrey RV Company		3200 E. Irvington Road	Tuscon	ΑZ	85714	520 889 6000
4VZAT1C996C052809 (52809	Tom Johnson Camping Center		1885 US 70 West	Marion	S	28752	828 724 4105
4VZAT1C956C052869 !	52869	North Trail RV Center		5270 Orange River Blvd	Fort Myers	귙	33905	239 693 8200
4VZAT1C916C052870 (52870	Gibbs	Thomas & Patricia	1252 Twin Points Rd	Hot Springs	AR	71913	501 525-2784
4VZAT1C936C052871 (52871	Hoggins	James E & Tania Lynn	59 Monarch Blvd	Hattiesburg	MS	39402	601 264-9377
4VZAT1C956C052872 (52872	North Trail RV Center		5270 Orange River Blvd	Fort Myers	귙	33905	239 693 8200
4VZAT1C976C052873 (52873	Lee's RV City Inc.		13111 N. Broadway Ext	Oklahoma City	ð	73114	405 936 9300
4VZAT1C966C052959 (52959	North Trail RV Center		5270 Orange River Blvd	Fort Myers	귙	33905	239 693 8200
	52960	Stinnett Tom Holiday RV Center Inc		520 Marriott Drive	Clarksville	Z	47129	812 282 7718
	52961	Alpin Haus		103 Sitterly Rd	Clifton Park	ž	12065	518 371 2211
4VZAT1C966C052962 (52962	Leisure Tyme RV		1490 Hwy 98 West	Mary Ester	귙	32569	850 581 0880
	52988	North Trail RV Center		5270 Orange River Blvd	Fort Myers	귙	33905	239 693 8200
	52989	Stinnett Tom Holiday RV Center Inc		520 Marriott Drive	Clarksville	Z	47129	812 282 7718
	52990	Wheelers RV Of Las Vegas		13175 Las Vegas Blvd S.	Las Vegas	⋛	89044	702 896 9000
	52991	Midway Motor		5590 S. Division Ave.	Grand Rapids	Ξ	49548	616 534 9641
4VZAT1C946C052992 (52992	Coachlight RV		5327 s. Garrison Ave.	Cathage	Ø	64836	417 358 7444
	53199	American RV		11810 Central S.E.	Albuquerque		87123	505 293 1983
	52253	Tom Schaeffers		1236 Pottsville Pike	Shoemakersville	_	19555	610 562 3071
	53435	North Trail RV Center		5270 Orange River Blvd.	Fort Myers	귙	33905	239 693 8200
	53361	North Trail RV Center		5270 Orange River Blvd	Fort Myers	귙	33905	239 693 8200
	53284	Wheelers RV Of Las Vegas		13175 Las Vegas Blvd S.	Las Vegas	≥ ;	89044	702 896 9000
	53283	American RV		11810 Central S.E.	Albuquerque	\[\frac{2}{2}\]	87123	505 293 1983
4VZAT1C996C053202 3	53201	voneelers RV Of Las Vegas North Trail RV Center		13175 Las Vegas Bivd S. 5270 Orange River Blvd	Las vegas Fort Mvers	≥ ⊒	33905	702 696 9000 239 693 8200
			7					
			- 1161					

	SALE							
	v	Last Name or						
VINNUM	ORDE	Company Name	First Name	Address	City	State	Zip	State Zip Phone
4VZAT1C996C052390 52390	52390	Beaudry RV Center		3200 E Irvington Rd	Tuscon	ΑZ	85714	520 889 6000
4VZAT1C936C052594 !	52594	Newmar						
4VZAT1C986C052963 (52963	Newmar						
4VZAT1C906C053203 (53203	Newmar						
4VZAT1C906C053282 (53282	Newmar						
4VZAT1C996C053362 (53362	Newmar						
4VZAT1C976C053490 (53490	Newmar						
4VZAT1C996C053491 (53491	Newmar						
4VZAT1C956C053598 (53598	Newmar						
4VZAT1C976C053599 (53599	Newmar						



Spartan Chassis, Inc. Customer Service Group

November 28, 2005

Re: Notice of Campaign Service Bulletin: CSB05-390-002

Dear RV Dealer,

A recent decision was made to issue a Campaign Service Bulletin for certain Newmars which addresses the condition of the air system being capable of dumping when the vehicle is traveling over 8 mph. This campaign should take .5 hours to complete.

Your satisfaction with our product is important to us. We are initiating this contact with you so that you will, at your earliest opportunity, take your vehicle in for service. In doing so, we can be certain that you have the best product available for optimal performance.

Carefully follow the instructions below:

Contact Spartan Chassis Customer Service 1-800-393-8861 (option 6); have your VIN (Vehicle Identification Number) available (this is listed on the upper left portion of the address label). A Spartan representative will advise you as to what your vehicle requires.

Although <u>this is not a recall</u>, Spartan Chassis is committed to serving you with your best interests in mind.

Best Regards,

Wayne Ridge Product Improvement Administrator Spartan Chassis, Inc.



Spartan Chassis, Inc. Customer Service Group

Should the servicing facility have any billing questions, call Wayne Ridge at 517-543-6400 ext.445