72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007

TECHNICAL SERVICE BULLETIN										
DATE ISSUED		MODEL YEAR(S) AFFECTED		Model(s) Affected			TSB#			
02/12/2010		2011		MA DP			366			
Brand								Түре		
All Sco		□ American Star Dutch Star Kountry Star □ Northern Star			Mountain Aire Kountry Aire Essex London Aire	F	l □ W□ P⊠	TT □ CA□ DB□		
	Air Conditioning & Heating Appliances & Accessories Cabinets & Furniture Chassis Components Construction Components				 □ Electrical Components □ Exterior Components □ Interior Components □ Plumbing & Bath Components □ Windows, Awnings, Vents, & Doors 					
DESCRIPTION OF PROBLEM Newmar Corporation intends to ship the 2011 Mountain Aire Deisel Pusher with the protective film over the chrome										
		elow) This is being done to m during the washing of the	inimize	damage a	t Newmar, during trans					

800.858.4924 FAX 219.773.2007

NEWMAR CORPORATION WARRANTY DEPARTMENT

RECOMMENDED SOLUTION

The Protective Film on the 2011 Mountain Aire Diesel Pusher front bumpers, rear taillights & grills <u>MUST BE REMOVED FROM THE CHROME STRIPS BY THE DEALERSHIPS AFTER THE COACH HAS BEEN</u>
CHECKED IN AND WASHED.



