72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007

| TECHNICAL SERVICE BULLETIN | | | | | |
|---|--|-----------------------|-----------------------|----------------------|--|
| DATE ISSUED | MODEL YEAR(S) AFFECTED | Model(s) Affected | | TSB# | |
| 10/24/95 | 10/24/95 1996 | | ALL | | |
| Brand | | | Түре | | |
| All 🗖 Americ | can Star 🗖 Kountry Star 🖣 | Dutch Star | All \square T | T D FW D | |
| NewAire □ Mountain Aire ■ Kountry Aire ■ | | London Aire ■ | C A ■ D | P■ DB□ | |
| ■ Air Conditioning & | ☐ Electrical Components | | | | |
| ☐ Appliances & Accessories | | ☐ Exterior Components | | | |
| ☐ Cabinets & Furniture | | ☐ Interior Co | ☐ Interior Components | | |
| ☐ Chassis Componer | ☐ Plumbing & Bath Components | | | | |
| ☐ Construction Com | ☐ Windows, Awnings, Vents, & Doors | | | | |
| DESCRIPTION OF PROBLEM There is no way to unplug the Danby icemaker or to turn off the icemaker. | | | | | |
| | | | | | |
| RECOMMENDED SOLUTION | | | | | |
| not an access to unplug | ot come with an on/off switch rest the icemaker, cut out a panel besing pay .5 hour to make this repair. I | de the icemaker to | gain access to th | ne recept behind the | |

NEWMAR CORPORATION WARRANTY DEPARTMENT

