72185 COUNTY ROAD 3 NAPPANEE, IN 46550

## NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007

TECHNICAL SERVICE BULLETIN						
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S)	Model(s) Affected		TSB#	
6/6/97	1997	ALL			142	
BRAND			Түре			
All	ican Star 🛘 Kountry Star 🗖	Dutch Star	All $\square$	ТТП	$F  W   \square$	
NewAire □ Mount	tain Aire  Kountry Aire	London Aire	САП	D₽■	DB ■	
☐ Air Conditioning & Heating ☐ Ele			Components			
☐ Appliances & Accessories ☐			Exterior Components			
☐ Cabinets & Furniture ☐ Interio			Components			
■ Chassis Compone	☐ Plumbing a	☐ Plumbing & Bath Components				
☐ Construction Con	☐ Windows,	☐ Windows, Awnings, Vents, & Doors				
	DESCRIPTION (	OF PROBLEM				
	RECOMMENDE	D SOLUTION				
measurement is taken f it at 3/16". If you have height according to the The rear axle ride heigh	rtan independent front suspension from the centerline to the centerline customers who complain of front above parameters. In the will remain at 8 ½" measured front your Newstions, please contact your Newstions.	e of the shock mo t axle ride quality om the bottom of	ounting bolts. Non the IFS, che	Newmar cu ck and adju	rrently sets ust the ride	