TECHNICAL SERVICE BULLETIN								
DATE ISSUED	TE ISSUED MODEL YEAR(S) AFFECTED		)	MODEL(S) AFFECTED			TSB #	
12/5/97	ALL			ALL			152	
BRAND					Түре			
All Americ	can Star 🛛	Kountry Star 🛛	Dut	ch Star 🛛	All 🗖 🕺	ГТ 🗖	FW 🗖	
NewAire 🛛 Mountain Aire 🗖 Kountry Aire 🗖			Lor	don Aire 🗖		⊃P□	D В 🗖	
□ Air Conditioning & Heating □ B					omponents			
Appliances & Accessories				Exterior Components				
□ Cabinets & Furniture				Interior Components				
□ Chassis Components				Plumbing & Bath Components				
Construction Components				☐ Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM Kwikee step.								
RECOMMENDED SOLUTION								
Kwikee requests that th	ey be contact				9961.			

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.