

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #				
12/08/98	ALL	CLASS A'S WITH A TAG AXLE	168				
BRAND		TYPE					
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input checked="" type="checkbox"/>	Dutch Star <input checked="" type="checkbox"/>	All <input type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>	
NewAire <input type="checkbox"/>	Mountain Aire <input checked="" type="checkbox"/>	Kountry Aire <input checked="" type="checkbox"/>	London Aire <input type="checkbox"/>	C A <input checked="" type="checkbox"/>	D P <input type="checkbox"/>	D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components			
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components			
<input checked="" type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
Granning tag axle maintenance schedule.							
RECOMMENDED SOLUTION							
This is a reminder to dealers to inform new and current customers that have units with a Granning tax axle that routine maintenance is required at 3,000 miles, 12,000 miles, and at every 12,000-mile interval. Please see the Granning owner's manual that was included in the Owner's Information Packet.							

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.