
72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 574.773.2007

TECHNICAL SERVICE BULLETIN							
DATE ISSUED MODEL Y		EAR(S) AFFECTED MODEL(S)		AFFECTED	TSB#		
2/18/02	All			All		237	
Brand			•	Түре			
All Americ	can Star 🛚	Kountry Star	Dut	ch Star 🛚	All T	T□ FW□	
NewAire □ Mountain Aire □ Kountry Aire □			Lon	don Aire□	C A 🗆 D	PD DBD	
☐ Air Conditioning & Heating ☐ Electrical Components					omponents		
☐ Appliances & Accessories				☐ Exterior Components			
☐ Cabinets & Furniture				☐ Interior Components			
☐ Chassis Components				☐ Plumbing & Bath Components			
■ Construction Components				☐ Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
Slideout room adjustme	ents.						
RECOMMENDED SOLUTION							
Newmar is requesting that the servicing technician complete the attached warranty slide out adjustment documentation submittal form when performing any slideout room adjustment. This form will be required for payment of warranty claims when any slideout adjustment is made. The information will then be forwarded to the Newmar Engineering Department for review. By gathering this information Newmar hopes to greatly reduce the need for slideout room adjustments. The following flat rate codes and times will apply: 40822402 Non flat floor main slide 1.0 40822403 Flat floor main slide 1.0 40822404 Wardrobe slide 1.0 40822405 Bedroom slide 1.0							

NEWMAR CORPORATION WARRANTY DEPARTMENT



NEWMAR CORPORATION WARRANTY DEPARTMENT

