800.858.4924 Fax 219.773.2007

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN									
DATE ISSUED		MODEL YEAR(S) AFFECTED			Model(s) Affected			TSB#	
6/17/87		1987 – PRESENT			ALL			4	
Brand				•	Түре				
All	☐ Americ	can Star 🛚	Kountry Star 🛚	Dut	ch Star 🛚	All	ТТП	FW □	
NewAire □ Mountain Aire □ Kountry Aire ■				Lon	don Aire■	САП	D₽□	DB 🗖	
☐ Air Conditioning & Heating					☐ Electrical Components				
☐ Appliances & Accessories					Exterior Components				
☐ Cabinets & Furniture					Interior Components				
☐ Chassis Components					Plumbing & Bath Components				
☐ Construction Components					Windows, A	Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM									
Sewage n	nse operation.								
RECOMMENDED SOLUTION									
	pen sewage va								
	2. Hook up hose to sewage rinse.								
	3. Turn water pressure on hose.4. Leave water on for 10-15 minutes.								
	4. Leave water on for 10-15 minutes.5. Turn water pressure off and tank should be clean.								
5. Turn water pressure ou and tank should be clean.									