


NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #				
7/17/92	1992-1993	ALL	58				
BRAND		TYPE					
All <input checked="" type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input type="checkbox"/>	T T <input checked="" type="checkbox"/>	F W <input checked="" type="checkbox"/>	
NewAire <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input type="checkbox"/>	C A <input type="checkbox"/>	D P <input type="checkbox"/>	D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating				<input checked="" type="checkbox"/> Electrical Components			
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components			
<input type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
Correct 7-9 way plug hook up for tow vehicles.							
RECOMMENDED SOLUTION							
Prints enclosed show 7-9 way hook up.							

NEWMAR CORPORATION WARRANTY DEPARTMENT

DATE	BY	REVISION	CHK



1980
P011002

NEWMAR INDUSTRIES, INC.
COUNTRY AIRE -
TITLE: CAREND OF RUNNING
SCALE: NONE
DATE: 7-24-78
DRAWN BY: EJS

NOTE:
FRONT VIEW OR MALE
PART SHOWN - (WIRE CONNECTIONS
ON BACK SIDE)