

# NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN																			
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #											
7/6/94		1994			ALL			96											
BRAND					TYPE														
All	<input type="checkbox"/>	American Star	<input type="checkbox"/>	Kountry Star	<input checked="" type="checkbox"/>	Dutch Star	<input checked="" type="checkbox"/>	All	<input checked="" type="checkbox"/>										
NewAire	<input type="checkbox"/>	Mountain Aire	<input type="checkbox"/>	Kountry Aire	<input type="checkbox"/>	London Aire	<input checked="" type="checkbox"/>	T T	<input type="checkbox"/>										
								F W	<input type="checkbox"/>										
								C A	<input type="checkbox"/>										
								D P	<input type="checkbox"/>										
								D B	<input type="checkbox"/>										
<table border="0"><tr><td><input type="checkbox"/> Air Conditioning &amp; Heating</td><td><input type="checkbox"/> Electrical Components</td></tr><tr><td><input type="checkbox"/> Appliances &amp; Accessories</td><td><input type="checkbox"/> Exterior Components</td></tr><tr><td><input type="checkbox"/> Cabinets &amp; Furniture</td><td><input type="checkbox"/> Interior Components</td></tr><tr><td><input type="checkbox"/> Chassis Components</td><td><input checked="" type="checkbox"/> Plumbing &amp; Bath Components</td></tr><tr><td><input type="checkbox"/> Construction Components</td><td><input type="checkbox"/> Windows, Awnings, Vents, &amp; Doors</td></tr></table>										<input type="checkbox"/> Air Conditioning & Heating	<input type="checkbox"/> Electrical Components	<input type="checkbox"/> Appliances & Accessories	<input type="checkbox"/> Exterior Components	<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components	<input type="checkbox"/> Chassis Components	<input checked="" type="checkbox"/> Plumbing & Bath Components	<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors
<input type="checkbox"/> Air Conditioning & Heating	<input type="checkbox"/> Electrical Components																		
<input type="checkbox"/> Appliances & Accessories	<input type="checkbox"/> Exterior Components																		
<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components																		
<input type="checkbox"/> Chassis Components	<input checked="" type="checkbox"/> Plumbing & Bath Components																		
<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors																		
DESCRIPTION OF PROBLEM																			
Slow filling fresh water tanks. Water shut off valve could be installed backwards.																			
RECOMMENDED SOLUTION																			
Water valve installed wrong to shut off water to fresh water tank. Turn valve around so arrow points toward fresh water tank.																			

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.